Exercise 14-12

1. Open drawing EX14-11 created in Exercise 14-11.

2. Turn live sectioning on for the section object, if it is not already on.

3. Display the cutaway geometry in a contrasting color.

4. Change the transparency of cutaway geometry to a low percentage and then to a high percentage.

5. Change the intersection fill to an ANSI hatch pattern.

6. Save the drawing as EX14-12.