

Exercise 11-3

1. Continue from Exercise 11-2 or start AutoCAD.
2. Start a new drawing from scratch or use a decimal-unit template of your choice. Save the drawing as EX11-3.
3. Use the **Distance** option of the **CHAMFER** command to draw the objects shown in Figure 11-4.
4. Draw the “Process” objects shown in Figure 11-5. Use the **Distance** option of the **CHAMFER** command to change them to the “Result” objects.
5. Draw the “Process” object shown in Figure 11-6. Use the **Angle** option of the **CHAMFER** command to create the “Result” object.
6. Resave and close the file.
7. Keep AutoCAD open for the next exercise, or exit AutoCAD if necessary.