

Exercise 1-1

See the drawing act01-01a.dwg available on the companion website.

1. Study the multiview sketch shown below.
2. Each tick mark represents one unit. Use the correct dimensions as given in the multiview sketch.
3. Freehand sketch the object in a pictorial view using the axes of a 3D coordinate system. (Plot the AutoCAD drawing act01-01a.dwg.)

To continue practicing sketching, complete act01-01b.dwg available on the companion website.

