

Exercise 12-2

1. Continue from Exercise 12-1 or start AutoCAD.
2. Start a new drawing from scratch or use a decimal-unit template of your choice. Save the drawing as EX12-2.
3. Draw a 2.25-unit square.
4. Rotate the square 75°.
5. Use the **Reference** option to rotate the square another 45°.
6. Rotate the square back to 0°.
7. Resave and close the file.
8. Keep AutoCAD open for the next exercise, or exit AutoCAD if necessary.